JUUZST.

C-0-1-2-1-	,	-A-L SEE BOTTO	OM OF PAGE F	OR SPECIAL CONTROLS, IF ANY	
INFORM	ATION	REPORT	Netions meanin	cterial contains information affecting the al Defense of the United States within the g of the Espionage Laws, Title 18, U.S.C.	
PREPARED AND DISSEMINATED BY				Secs. 783 and 784, the transmission or revelation of which in any manner to an unauthorized per-	
CENTRAL IN	NTELLIGE	NCE AGENCY		prohibited by law	2
China					2
UBJECT			DATE DI	STRIBUTED	
Port Information		a 1		1 100 1956	
NAVY review completed	(*)		NO. OF	PAGES NO. OF ENGLS.	
			SUPPLE	MENT TO REPORT #	
					2
					-
	THE	S IS UNEVALUATED II	NEORMATION		2
THE OFFICE OF H	AVAL INTE	LLIGENCE FURNISHED	THE FOLLOWI	NG INFORMATION TO CIA	
TOP TAC DISCUSCING	ATTOW TH	ACCORDANCE UTINE DA	BACIBARY 3 C	OF NSCID #7 (DIO, 8ND	
	RITOR IN	ACCORDINGS WITH PA	DECEMBER 2 C	OF MOCID #1 (DIO, OND	
11 0 175-56) <u>.</u> 7				*	
					2
					_
2. Alphabetical Des	imetore	In connection with	h information	n contained hemein	
Z. Alphabetical bes	TRIBLOOFS	In connection with	u intormecto	py of HO Chart No 5392	
and referred to	in this r	eport by the follo	ATER STREET	tical designators:	
		ssel anchored			
	B. Ri	ver steamer landin	g .		
	C. Be				
	D. Na	val station area			
	E. Sh				
		ipway			
		angnan Shipyard		_	
		re slipways		<u> </u>	- 1
<1-		all drydock	40		、 \
		ree "river gunboat	s"		1
		inese vessels		C)	1.
7	L.	vessel		Ľ.	ر و
	M.	vessel		12	
		cranes		77	0
		rehouse or manufac	turing plant	K	
		on works		\mathcal{H}	2
45		rge factory		7	Ś
	-Z- 248				
3. Approaches and P.	ilot Date				_ ^/
J. Alle Carones and E.				[2!
					ſΛŃ
	haam# 45 -		************		~ <i>y</i>
		vessel for naviga			
the vessel's char	rt did no	t accurately show	the position	s or buoys.	
3	ad Alba			To ad 14 data was a second	
also inaccurate	with resp	ect to buoy position	ons and port	facilities. Vesse	
	-				
	1	C-O-N-F-1-D-E-H-T	-I-k-L		
	1	C-U-N-F-I-D-E-N-P	-laket		
STATE ARMY	HAVY		FBI FBI		
STATE ARMY	RAVY	DISTRIBUTION	(1)		

LIMITED: Dissemination limited to full-time employees of CIA, AEC and FBI; and, within State and Defense, to the intelligence compositions producing NIS elements, and higher echelons with their immediate supporting states. Not to be disseminated to consultants, external projects or reserve personnel on short term active duty (excepting individuals who are normally full-time employees of CIA, AEC, FBI, State or Defense) unless the written permission of the originating office has been obtained through the Assistant Director for Collection and Dissemination, CIA.

٠. ٠	C-O-N-F-I-D-E-H-T-I- A-L	25X
	-2-	
		25)
pi.	e pilot boarded the vessel 291815H "between outer and second buoy." The lot arrived via a steamer and was transferred in one of	25X
OD	Pilotage at subject port is compulsory. structions during the approach and reported the depth of the channel was	25 X 1
25 por	ifficient for the vessel. The vessel's entering drafts (fresh water) were "4" forward and 25"1" aft. Just prior to the vessel's departure from subject art, a pilot and control party boarded the vessel at 060600H Apr 56. The pilot is discharged 061240H "between first and second port buoys." The pilot was "raw," evidently lacked experience, and appeared nervous.	25X
fr	Cold weather and rain were encountered throughout the vessel's call at subject port. Wind warious directions at velocities between force four and force five was so encountered. The average temperature during the call was about 57°F.	
. An	chorages and Controls Vessel anchored 291848H "between second and third" oys until 292158H when it again got underway.	25)
300 six	Vessel again anchored at 00100H at Wu-Sung. A boarding party consisting of 12 port officials and x military personnel boarded the vessel at 300200H. All six military perment carried pistols. Radios, binoculars, cameras, flares, sextant, vessel's dar, and some provisions were placed under seal. Crew members were mustered	25)
in The soi the in Ve	the saloon. A thorough search was made of the vessel "possibly for weapons." the boarding party departed from the vessel 300430H leaving two military permunel aboard the vessel as guards. The two guards remained aboard the vessel troughout the call. Vessel got underway 300440H and proceeded to a position the river "between buoys four and five," position labeled designator A. assel arrived at designator A 310830H.	
fe mo ri	approximately ten large diesel-powered gs at subject port. All tugs were painted dark, olive green, were about 100 set in length, and appeared to be in good condition. Several lighters and stor sampans were also seen. No dredges or salvage vessels were observed. A ver steamer landing, position labeled designator B, was in constant use for the cargo and passengers.	25>
one por ver and in of	rgo Operations and Berth Commencing 312200H, vessel discharged approximately in-third of the total cargo aboard to lighters. This operation occurred at sition labeled designator A and was completed at 031400H Apr 56. At 031700H, issel assisted by three tugs got underway for her berth, labeled designator C, discrete at 031900H. Berth was alongside a pontoon wharf as sketched a Figure 6a. Discharging operations resumed at 031900H with two to five gangs at stevedores unloading the cargo from the vessel in UNCODEDshifts. Each and consisted of 12 men who were given periodic rest breaks. All stevenores	050
do:	re young - apparently between the ages of 20 and 30. steve- res were not very efficient probably due to the fact they were not used to evedoring. Most of the stevedores normally worked as railway employees. The	25)
to and in hor via bus 05%	rgo was first carried from the vessel to the pontoon wharf and from there a shed. The shed was about 500 feet in length and constructed of mat sides d roof. When the shed had been filled to capacity, the cargo was then loaded railway cars. On several occasions the stevedores had to wait two to five curs for a railway car to become available for loading. Miscellaneous prosions of good quality and reasonable prices were bought by the vessel. No makers were purchased at subject port. Discharging operations were completed 2120H. A pilot and control party consisting of six port officials and four litary personnel boarded the vessel at 060600H. Control party departed the essel at 060650H and the vessel got underway from berth at 060710H.	
Co	no new construction in subject port.	25)
la	wal Installations a "naval station area" exists in area beled designator D. Three to five "river gunboats" were moored alongside to station. no information concerning naval installa-	25)
	ons in the Wu-Sung area.	25X
NO	FORN C-O-NOFDISSEE-REROADA-L LIMITED	

t	C-O-N-F-I-D-E-H-T-I-A-L	05)//
	- 3 ₋	25 X 1
9.	Shipbuilding and Ship Repair A large shippard was reported in the area labeled designator E. About five "river boats" were undergoing repairs including red-leading in the shippard. One new boat, reportedly the largest in the yard, was estimated to be about 220 feet in length overall. The boat was being finished in the river alongside the only slipway at the shippard. Slipway is labeled designator F. otUNCODED may have been sunk during World War II and were just raised for rebuilding. Area designated G indicates rough limits of the Kiangnan Shippard. Five slipways at the Kiangnan Shippard are designated H. the slipways could accommodate vessels up to "river boat" size. No heavy-duty steel cranes were observed in the area; only old-type wooden gaff and boom cranes were seen. An area which appeared to be a small drydock was observed at position labeled designator I.	25X1 25X1
10.	three "river gumboats" at position labeled designator J. Vessels were moored alongside the Kiangnan Shipyard. Vessels were about 200 feet long, had one stack, and appeared suitable for all-weather coastal navigation purposes. Vessels armament was not noted. Three to five of the same type boats were moored alongside the "naval station area" designated D. No other naval vessels were observed.	25X1 25X1 25X1
11.	Merchant Vessels Five or six Chinese coastal vessels of two-three thousand gross tons each were anchored in the river at positions designated by K. One of the Chinese vessels was waiting to discharge coal; the others were waiting to discharge general cargo. merchant vessel of about eight thousand gross tons was moored at position labeled designator L. vessel of about six thousand gross tons was sighted at M. least two river boats" arrived daily at subject port, each loaded with about three thousand tons of coal for discharge. some of the coal was discharged at the buoys to lighters. The same boats also brought passengers to subject port. Apparently, the boats left subject port in ballast after discharging the coal and passengers.	25X1 25X1 25X1 25X1 25X1
12.	Shore Activities Crew members were allowed ashore upon presentation of their Seamen's Book and the shore pass issued by the control party that had boarded the vessel on arrival. The majority of the crew participated in shore liberty. A Seamen's Club is present in subject port and some crew members went there for recreation. A 2300 curfew was in effect in subject port, but it was not strictly enforced.	
13.	Miscellaneous Two cab-type boom cranes were sighted at position labeled designator N. A warehouse or manufacturing plant was seen at position labeled designator 0. The building had two smoke stacks from which brown smoke was seen coming out. the building was being used as a textile plant. a large factory in the general area labeled designator Q. Factory was well-built and of steel construction. Several smoke stacks were attached to the building and a great deal of activity was observed in the vicinity of the factory. All persons encountered in subject port appeared healthy and well-fed. However, no one would accept even a cigarette from a foreigner. Many of the poor families live aboard sampans in the river and use the river for washing, drinking, and dumping severage. No activity was observed at Iron Works, position labeled designator P.	25X1 25X1
	- end -	

C-O-N-F-I-D-E-N-T-I-A-L

NO DISSEM ABROAD

LIMITED

NOFORN









